## Texas Commission on Environmental Quality Cross-Connection Control Subcommittee June 6, 2019

## Building F, Room 2210

Time: 9:00 – 3:00

9:00 Announcements

Mr. Charlie Middleton

Introductions

Adoption of previous meeting summary

9:15 Program Updates:

Cross-Connection Control Program

Mr. Charlie Middleton

Landscape Irrigation

Mr. Al Fuentes

IAC Rule Petition Update

Mr. Al Fuentes

Occupational Licensing

Ms. Linda Saladino/Ms.

Tamara Calhoun

• BPAT and CSI experience considerations and process for licensing.

10:30 Break

10:45 LF 289 Spill-Resistant AVB: point-of-use untestable device, stamped as "SVB", let's have a look.

11:00 DIY Sprinkler Systems

Mr. James Garvin

Mr. Charlie Middleton

11:30 Annual testing requirements. Are purveyors using the most recent test date, installation date, or date of

first test to determine the due date of the next test?

12:00 Working Lunch

- BPATs and/or CSIs representing themselves as TCEQ inspectors.
- Impact of potential Plumbing Board dissolution on Cross-Connection Control
- Topics for next meeting?

## 1:00 Group Discussion:

BPAT tests an RP, the RP passes, both checks held tight with adequate pressure, etc. However, the tester checks the <u>NO</u> box for "Is the assembly installed in accordance with the manufacturers recommendations and/or local codes" and checks the "TEST RESULT" box as <u>failed</u>.

Should this be a failed test? Thoughts?

- 1:30 Licensed plumbers who have a WSPS conducting a TCEQ required CSI on their own plumbing work.
- 2:00 Cross Connection Control Program Surveys

Ms. Katherine McGlaughlin

- 2:30 Other Topics to Discuss?
- 3:00 Adjourn